


YMCA of Newfoundland and Labrador

Avalon Peninsula Region
 35 Ridge Road, P.O. Box 21291
 St. John's, NL A1A 5G6
 Tel: 709-726-9622
 www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site St. Peter's SACC Jan 7/25

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
Exits:		
Signage present		<u>SW</u>
Width, wheelchair accessibility		<u>SW</u>
Fire Control	<u>N/A</u>	<u>SW</u>
Direction of openings	<u>outside door outwards</u>	<u>SW</u>
Mechanical hardware		<u>SW</u>
Doors kept close	<u>outside door closed + locked</u>	<u>SW</u>
Ergonomics:		
Repetitive movements required	<u>will post</u>	<u>SW</u>
Use proper lifting techniques		<u>SW</u>
Stacking/Storage:		
Safe storage area and containers	<u>Well Organized</u>	<u>SW</u>
Safe arrangement of equipment and materials		<u>SW</u>
Equipment in safe working Condition		<u>SW</u>
Aisles/Passageways:		
Clear of clutter	<u>All Clear</u>	<u>SW</u>
Adequate lighting		<u>SW</u>
No tripping hazards	<u>path ways clear</u>	<u>SW</u>

Building healthy
 communities



Checklist Items	Comments	Staff Initials
Dangerous Substances:		
Have been identified	labeled	SW
Emergency plan in place		SW
Sanitation		SW
Washrooms meet standards		SW
MSDS posted	Posted	SW
Electrical:		
Switches and outlets have plate covers		SW
Electrical cords in good condition		SW
Emergency Preparedness:		
Emergency plan in place		SW
Stocked first aid kits available		SW
Regularly inspected fire extinguishers/alarms	Nov 2024	SW
Playground:		
Check for ice control	NIA	SW
Check for foreign objects		SW
Check playground equipment		SW
Check surfaces		SW
Check gate latches		SW
Other:		
	very little - to heat in room reported to NL Schools	SW
	- part of ceiling tile missing. ceiling with tile ceiling w/ damage outside bathroom.	
Date of inspection:	Jan 7, 24	
Inspected by:	S. White Melee	