



Admirals Academy
July 13, 2023

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
Exits:		
Signage present	_____	_____
Width, wheelchair accessibility	_____	_____
Ice Control	NIA	_____
Direction of openings	_____	_____
Mechanical hardware	_____	_____
Doors kept close	_____	_____
Ergonomics:		
Repetitive movements required	_____	_____
Use proper lifting techniques	_____	_____
Stacking/Storage:		
Safe storage area and containers	_____	_____
Safe arrangement of equipment and materials	_____	_____
Equipment in safe working condition	_____	_____
Aisles/Passageways:		
Clear of clutter	_____	_____
Adequate lighting	_____	_____
No tripping hazards	_____	_____



Checklist Items

Comments

Staff Initials

Dangerous Substances:

Have been identified

[Handwritten signature]

Emergency plan in place

Sanitation

Washrooms meet standards

MSDS posted

Electrical:

Switches and outlets have plate covers

[Handwritten signature]

Electrical cords in good condition

Emergency Preparedness:

Emergency plan in place

Stocked first aid kits available

Regularly inspected fire extinguishers/alarms

[Handwritten signature]

Playground:

Check for ice control

N/A

Check for foreign objects

Check playground equipment

Check surfaces

Grass very high

Check gate latches

[Handwritten signature]

Other:

[Handwritten mark]

Date of inspection: July 13, 2023

Inspected by: Jennifer Woodford *[Handwritten signature]*



Bay Roberts
Primary

July 7, 2023

YMCA of Newfoundland and Labrador

Avalon Peninsula Region
35 Ridge Road, P.O. Box 21291
St. John's, NL A1A 5G6
Tel: 709-726-9622
www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

Checklist Items Comments Staff Initials

Exits:

Signage present _____
Width, wheelchair accessibility _____
Ice Control _____
Direction of openings _____
Mechanical hardware _____
Doors kept close _____

N/A

[Handwritten initials]

Ergonomics:

Repetitive movements required _____
Use proper lifting techniques _____

[Handwritten initials]

Stacking/Storage:

Safe storage area and containers _____
Safe arrangement of equipment
and materials _____
Equipment in safe working
Condition _____

[Handwritten initials]

Aisles/Passageways:

Clear of clutter _____
Adequate lighting _____
No tripping hazards _____

Bag of Balls on floor
told staff to keep hung
on hook out of
way

[Handwritten initials]



Checklist Items

Comments

Staff Initials

Dangerous Substances:

Have been identified

[Handwritten initials]

Emergency plan in place

Sanitation

Washrooms meet standards

MSDS posted

Electrical:

Switches and outlets have plate covers

[Handwritten initials]

Electrical cords in good condition

Emergency Preparedness:

Emergency plan in place

Stocked first aid kits available

Regularly inspected fire extinguishers/alarms

[Handwritten initials]

Playground:

Check for ice control

_____ *NIA* _____

Check for foreign objects

Check playground equipment

Check surfaces

Check gate latches

_____ *NIA* _____

[Handwritten initials]

Other:

Date of inspection: July 7, 2023

Inspected by: Jeaniter Woodford *[Signature]*



YMCA of Newfoundland and Labrador

Avalon Peninsula Region
35 Ridge Road, P.O. Box 21291
St. John's, NL A1A 5G6
Tel: 709-726-9622
www.ymcanl.com CRA#108225533RR0001

YMCA Pre-K Bishop Abraham
Location.

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
Exits:		
Signage present	✓	JB
Width, wheelchair accessibility	✓	JB
Ice Control	N/A	JB
Direction of openings	✓	JB
Mechanical hardware	✓	JB
Doors kept close	✓	JB
Ergonomics:		
Repetitive movements required	✓	JB
Use proper lifting techniques	✓	JB
Stacking/Storage:		
Safe storage area and containers	✓	JB
Safe arrangement of equipment and materials	✓	JB
Equipment in safe working Condition	✓	JB
Aisles/Passageways:		
Clear of clutter	✓	JB
Adequate lighting	✓	JB
No tripping hazards	✓	JB



Checklist Items

Comments

Staff Initials

Dangerous Substances:

Have been identified	✓	JB
Emergency plan in place	✓	JB
Sanitation	✓	JB
Washrooms meet standards	✓	JB
MSDS posted	✓	JB

Electrical:

Switches and outlets have plate covers	✓	JB
Electrical cords in good condition	✓	JB

Emergency Preparedness:

Emergency plan in place	✓	JB
Stocked first aid kits available	✓	JB
Regularly inspected fire extinguishers/alarms	✓	JB

Playground:

Check for ice control	N/A	JB
Check for foreign objects	✓	JB
Check playground equipment	N/A	JB
Check surfaces	✓	JB
Check gate latches	N/A	JB

Other:

_____	_____
_____	_____
_____	_____
_____	_____

Date of inspection: Friday, July 7, 2023

Inspected by: Francis Bowen



YMCA Pre-K - East Point
 Elementary Location

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
Exits:		
Signage present	✓	JB
Width, wheelchair accessibility	✓	JB
Ice Control	N/A	JB
Direction of openings	✓	JB
Mechanical hardware	✓	JB
Doors kept close	✓	JB
Ergonomics:		
Repetitive movements required	✓	JB
Use proper lifting techniques	✓	JB
Stacking/Storage:		
Safe storage area and containers	✓	JB
Safe arrangement of equipment and materials	✓	JB
Equipment in safe working Condition	✓	JB
Aisles/Passageways:		
Clear of clutter	✓	JB
Adequate lighting	✓	JB
No tripping hazards	✓	JB



Checklist Items

Comments

Staff Initials

Dangerous Substances:

Have been identified	<u>✓</u>	<u>JB</u>
Emergency plan in place	<u>✓</u>	<u>JB</u>
Sanitation	<u>✓</u>	<u>JB</u>
Washrooms meet standards	<u>✓</u>	<u>JB</u>
MSDS posted	<u>✓</u>	<u>JB</u>

Electrical:

Switches and outlets have plate covers	<u>✓</u>	<u>JB</u>
Electrical cords in good condition	<u>✓</u>	<u>JB</u>

Emergency Preparedness:

Emergency plan in place	<u>✓</u>	<u>JB</u>
Stocked first aid kits available	<u>✓</u>	<u>JB</u>
Regularly inspected fire extinguishers/alarms	<u>✓</u>	<u>JB</u>

Playground:

Check for ice control	<u>N/A</u>	<u>JB</u>
Check for foreign objects	<u>✓</u>	<u>JB</u>
Check playground equipment	<u>N/A</u>	<u>JB</u>
Check surfaces	<u>✓</u>	<u>JB</u>
Check gate latches	<u>✓</u>	<u>JB</u>

Other:

_____	_____
_____	_____
_____	_____
_____	_____

Date of inspection: Friday, July 7th 2023

Inspected by: Francis Bowen



YMCA of Newfoundland and Labrador

Avalon Peninsula Region
35 Ridge Road, P.O. Box 21291
St. John's, NL A1A 5G6
Tel 709-726-9622
www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

YMCA Pre-K Elizabeth Park Elementary location

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
Exits:		
Signage present	✓	JB
Width, wheelchair accessibility	✓	JB
Ice Control	N/A	JB
Direction of openings	✓	JB
Mechanical hardware	✓	JB
Doors kept close	✓	JB
Ergonomics:		
Repetitive movements required	✓	JB
Use proper lifting techniques	✓	JB
Stacking/Storage:		
Safe storage area and containers	✓	JB
Safe arrangement of equipment and materials	✓	JB
Equipment in safe working Condition	✓	JB
Aisles/Passageways:		
Clear of clutter	✓	JB
Adequate lighting	✓	JB
No tripping hazards	✓	JB

Checklist Items

Comments

Staff Initials

Dangerous Substances:

Have been identified	✓	<u>JB</u>
Emergency plan in place	✓	<u>JB</u>
Sanitation	✓	<u>JB</u>
Washrooms meet standards	✓	<u>JB</u>
MSDS posted	✓	<u>JB</u>

Electrical:

Switches and outlets have plate covers	✓	<u>JB</u>
Electrical cords in good condition	✓	<u>JB</u>

Emergency Preparedness:

Emergency plan in place	✓	<u>JB</u>
Stocked first aid kits available	✓	<u>JB</u>
Regularly inspected fire extinguishers/alarms	✓	<u>JB</u>

Playground:

Check for ice control	<u>N/A</u>	<u>JB</u>
Check for foreign objects	✓	<u>JB</u>
Check playground equipment	<u>N/A</u>	<u>JB</u>
Check surfaces	✓	<u>JB</u>
Check gate latches	<u>N/A</u>	<u>JB</u>

Other:

_____	_____
_____	_____
_____	_____
_____	_____

Date of inspection: Tuesday, July 11, 2023

Inspected by: Frances Bowen



YMCA of Newfoundland and Labrador

Avalon Peninsula Region
35 Ridge Road, P.O. Box 21291
St. John's, NL A1A 5G6
Tel: 709-726-9622
www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist *YMCA Pre-K Paradise Elementary Location*

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
Exits:		
Signage present	✓	<i>JB</i>
Width, wheelchair accessibility	✓	<i>JB</i>
Ice Control	N/A	<i>JB</i>
Direction of openings	✓	<i>JB</i>
Mechanical hardware	✓	<i>JB</i>
Doors kept close	✓	<i>JB</i>
Ergonomics:		
Repetitive movements required	✓	<i>JB</i>
Use proper lifting techniques	✓	<i>JB</i>
Stacking/Storage:		
Safe storage area and containers	✓	<i>JB</i>
Safe arrangement of equipment and materials	✓	<i>JB</i>
Equipment in safe working Condition	✓	<i>JB</i>
Aisles/Passageways:		
Clear of clutter	✓	<i>JB</i>
Adequate lighting	✓	<i>JB</i>
No tripping hazards	✓	<i>JB</i>



Checklist Items

Comments

Staff Initials

Dangerous Substances:

Have been identified	<u>✓</u>	<u>JB</u>
Emergency plan in place	<u>✓</u>	<u>JB</u>
Sanitation	<u>✓</u>	<u>JB</u>
Washrooms meet standards	<u>✓</u>	<u>JB</u>
MSDS posted	<u>✓</u>	<u>JB</u>

Electrical:

Switches and outlets have plate covers	<u>✓</u>	<u>JB</u>
Electrical cords in good condition	<u>✓</u>	<u>JB</u>

Emergency Preparedness:

Emergency plan in place	<u>✓</u>	<u>JB</u>
Stocked first aid kits available	<u>✓</u>	<u>JB</u>
Regularly inspected fire extinguishers/alarms	<u>✓</u>	<u>JB</u>

Playground:

Check for ice control	<u>N/A</u>	<u>JB</u>
Check for foreign objects	<u>✓</u>	<u>JB</u>
Check playground equipment	<u>N/A</u>	<u>JB</u>
Check surfaces	<u>✓</u>	<u>JB</u>
Check gate latches	<u>N/A</u>	<u>JB</u>

Other:

_____	_____
_____	_____
_____	_____
_____	_____

Date of inspection: Tues. July 11, 2023

Inspected by: Frances Bowen



Persalvic
School
Complex

YMCA of Newfoundland and Labrador

Avalon Peninsula Region
35 Ridge Road, P.O. Box 21291
St. John's, NL A1A 5G6
Tel: 709-726-9622
www.ymcanl.com CRA#108225533RR0001

July 7, 2023

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
Exits:		
Signage present		
Width, wheelchair accessibility		
Ice Control	N/A	N/A
Direction of openings		
Mechanical hardware		
Doors kept close		
Ergonomics:		
Repetitive movements required		
Use proper lifting techniques	yes	
Stacking/Storage:		
Safe storage area and containers		
Safe arrangement of equipment and materials	very organized	
Equipment in safe working Condition	Brought fan as Room very warm	
Aisles/Passageways:		
Clear of clutter		
Adequate lighting		
No tripping hazards		



Checklist Items

Comments

Staff Initials

Dangerous Substances:

Have been identified

J

Emergency plan in place

Sanitation

Washrooms meet standards

MSDS posted

Electrical:

Switches and outlets have plate covers

J

Electrical cords in good condition

Emergency Preparedness:

Emergency plan in place

Stocked first aid kits available

Regularly inspected fire extinguishers/alarms

J

Playground:

Check for ice control

Check for foreign objects

Check playground equipment

Check surfaces

Check gate latches

N/A
N/A
N/A
N/A

Other:

Date of inspection: July 7, 2023

Inspected by: Jennifer Woodford



Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
Exits:		
Signage present		AS
Width, wheelchair accessibility		AS
Ice Control	N/A	AS
Direction of openings		AS
Mechanical hardware		AS
Doors kept close		AS
Ergonomics:		
Repetitive movements required		AS
Use proper lifting techniques		AS
Stacking/Storage:		
Safe storage area and containers		AS
Safe arrangement of equipment and materials		AS
Equipment in safe working condition		AS
Aisles/Passageways:		
Clear of clutter		AS
Adequate lighting		AS
No tripping hazards		AS



Checklist Items

Comments

Staff Initials

Dangerous Substances:

Have been identified	_____	<u>AB</u>
Emergency plan in place	_____	<u>AB</u>
Sanitation	_____	<u>AB</u>
Washrooms meet standards	_____	<u>AB</u>
MSDS posted	_____	<u>AB</u>

Electrical:

Switches and outlets have plate covers	_____	<u>AB</u>
Electrical cords in good condition	_____	<u>AB</u>

Emergency Preparedness:

Emergency plan in place	_____	<u>AB</u>
Stocked first aid kits available	_____	<u>AB</u>
Regularly inspected fire extinguishers/alarms	_____	<u>AB</u>

Playground:

Check for ice control	N/A	<u>AB</u>
Check for foreign objects	_____	<u>AB</u>
Check playground equipment	_____	<u>AB</u>
Check surfaces	_____	<u>AB</u>
Check gate latches	N/A	<u>AB</u>

Other:

_____	_____
_____	_____
_____	_____
_____	_____

Date of inspection: July 11th, 2023

Inspected by: 