



Calvary  
Baptist  
SACC

Avalon Peninsula Region  
35 Ridge Road, P.O. Box 21291  
St. John's, NL A1A 5G6  
Tel: 709-726-9622  
www.ymcanl.com CRA#108225533RR0001

### Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
<b>Exits:</b>		
Signage present	_____	SW
Width, wheelchair accessibility	_____	
Ice Control	_____	
Direction of openings	_____	
Mechanical hardware	_____	
Doors kept close	_____	
<b>Ergonomics:</b>		
Repetitive movements required	_____	SW
Use proper lifting techniques	_____	
<b>Stacking/Storage:</b>		
Safe storage area and containers	_____	SW
Safe arrangement of equipment and materials	Chairs stacked around room, along walls	
Equipment in safe working Condition	_____	
	_____	
<b>Aisles/Passageways:</b>		
Clear of clutter	_____	SW
Adequate lighting	_____	
No tripping hazards	_____	



Checklist Items

Comments

Staff Initials

**Dangerous Substances:**

Have been identified

\_\_\_\_\_

SW

Emergency plan in place

\_\_\_\_\_

SW

Sanitation

\_\_\_\_\_

SW

Washrooms meet standards

\_\_\_\_\_

SW

MSDS posted

\_\_\_\_\_

SW

**Electrical:**

Switches and outlets have plate covers

\_\_\_\_\_

SW

Electrical cords in good condition

No Cords around  
site

SW

**Emergency Preparedness:**

Emergency plan in place

\_\_\_\_\_

SW

Stocked first aid kits available

\_\_\_\_\_

SW

Regularly inspected fire extinguishers/alarms

Aug 23

SW

**Playground:**

Check for ice control

\_\_\_\_\_

SW

Check for foreign objects

\_\_\_\_\_

SW

Check playground equipment

\_\_\_\_\_

SW

Check surfaces

\_\_\_\_\_

SW

Check gate latches

N/A

SW

**Other:**

Chairs stacked along  
3 walls appear  
secure, EHO here  
last year, did not  
require action at  
that time

SW

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Date of inspection: Dec 12/23

Inspected by: S. White Miller

