



YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site Checklist Items **Comments Staff Initials** Exits: Signage present Width, wheelchair accessibility (June) NIA Ice Control Direction of openings Mechanical hardware Doors kept close **Ergonomics:** Repetitive movements required Use proper lifting techniques Stacking/Storage: Chairs Stacked Safe storage area and containers Safe arrangement of equipment and materials Equipment in safe working Condition Aisles/Passageways: Clear of clutter Adequate lighting No tripping hazards



| Checklist Items | Comments | Staff Initials |
|---|---------------------------------------|----------------|
| | | |
| Dangerous Substances: | | |
| Have been identified | breach | _ <u>/ E</u> |
| Emergency plan in place | | |
| Sanitation | - | _ <u>(E</u> |
| Washrooms meet standards | | _ <u>le</u> |
| MSDS posted | | |
| | | |
| | | |
| Electrical: | | 16 |
| Switches and outlets have plate covers | | 15 |
| Electrical cords in good condition | | |
| Emergency Preparedness: | | |
| Emergency plan in place | | |
| Stocked first aid kits available | 7 | CE |
| Regularly inspected fire extinguishers/alarms | | |
| | | |
| Playground: | | |
| Check for ice control | NIA | <u>l</u> E |
| Check for foreign objects | | |
| Check playground equipment | * * * * * * * * * * * * * * * * * * * | <u>(E</u> |
| Check surfaces | | <u>le</u> |
| Check gate latches | non presen | E CE |
| | | |
| Other: | | |
| | | |
| | | |
| _ | | |
| | | |
| _ | | |
| | | |
| | | |

Date of inspection: 13/23
Inspected by Augustians

12 m