

YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm	#	2038622	Site
------	---	---------	------

Checklist Items	Comments	Staff Initials
Exits:	•	Th
Signage present		70
Width, wheelchair accessibility		<u> </u>
Ice Control	N/A	TB
Direction of openings	outwards	TB
Mechanical hardware	-	TB
Doors kept close		TB
Ergonomics:		
Repetitive movements required		TB
Use proper lifting techniques		TB
Stacking/Storage:		
Safe storage area and containers		TB
Safe arrangement of equipment		
and materials		TB
Equipment in safe working	D. Ko. I.	TB
Condition	Broken hinges need to be fixed on a Storage cabinety	10
	fixed on a storage cabinets	
Aisles/Passageways:		
Clear of clutter	, _k	TB
Adequate lighting		TO
No tripping hazards		TB
F.F. 0		

Checklist Items	Comments	Staff Initials	
Dangerous Substances:			
Have been identified	·	TB_	
Emergency plan in place	-	\underline{TB}	
Sanitation		_ <u>TB</u>	
Washrooms meet standards		\underline{TB}	
MSDS posted	needs to be post	rd TB	
Electrical:			
Switches and outlets have plate covers		TB	
Electrical cords in good condition	·	_ <u>TB</u>	
Emergency Preparedness:		~	
Emergency plan in place	·	$\underline{\underline{TB}}$	
Stocked first aid kits available	-	$\underline{}$	
Regularly inspected fire extinguishers/alarm	september 2023	<u>TB</u>	
Playground:		_	
Check for ice control		TB	
Check for foreign objects		TB	
Check playground equipment	Destroyed beach	TB	
Check surfaces			
Check gate latches		TB_	
Other:			
	Broken bench is a		
	Safety hazard for		
	Splinters and		
	tripping hazard. Is	_	
	being reported to t	he	
	School town this		
_	Broken Window in Cafeteria in process		
	of pein tixeg		
	- J - F		



Date of inspection: A	pril	16th

Inspected by: