



## YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

## **Licensed Child Care Workplace Inspection Checklist**

Firm # 2038622 Site Checklist Items **Comments Staff Initials** Exits: Signage present LE LE LE LE Width, wheelchair accessibility NIA Ice Control Direction of openings Mechanical hardware Doors kept close **Ergonomics:** Repetitive movements required Use proper lifting techniques Stacking/Storage: Safe storage area and containers Safe arrangement of equipment and materials Equipment in safe working Condition Aisles/Passageways: Clear of clutter Adequate lighting No tripping hazards



Checklist Items	Comments	Staff Initials
Dangerous Substances: Have been identified		
Emergency plan in place		
Sanitation		
Washrooms meet standards		$-\frac{lG}{l}$
MSDS posted		_ <u>(E.</u>
M3D3 bosted		
Electrical:		
Switches and outlets have plate covers		<u>CE</u>
Electrical cords in good condition	tucked beher	d LE
Electrical cords in good condition	tucked beher teachers work Ste	o /
Emergency Preparedness:	WORK SHO	1762
Emergency plan in place		<u>l</u> E
Stocked first aid kits available		<u>(E</u>
Regularly inspected fire extinguishers/alarms		
Regularly hispected in a extinguishers, distinct		
Playground:		_
Check for ice control	NA	
Check for foreign objects		
Check playground equipment		
Check surfaces		
Check gate latches	yro lateles.	
Other:		<b>a.</b>
-	curtain unho	- Cled
-	In many pla	ces.
-	Ly reported	
-	to school.	

Inspected by: 20/23

8

ie.