



Roncalli  
SACC

**YMCA of Newfoundland and Labrador**

Avalon Peninsula Region  
35 Ridge Road, P.O. Box 21291  
St. John's, NL A1A 5G6  
Tel: 709-726-9622  
www.ymcanl.com CRA#108225533RR0001

**Licensed Child Care Workplace Inspection Checklist**

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
<b>Exits:</b>		
Signage present		LE
Width, wheelchair accessibility		LE
Ice Control	NIA	-
Direction of openings	outward	LE
Mechanical hardware		LE
Doors kept close		LE
<b>Ergonomics:</b>		
Repetitive movements required		LE
Use proper lifting techniques		LE
<b>Stacking/Storage:</b>		
Safe storage area and containers		LE
Safe arrangement of equipment and materials		LE
Equipment in safe working condition		LE
<b>Aisles/Passageways:</b>		
Clear of clutter		LE
Adequate lighting		LE
No tripping hazards		LE



**Checklist Items**

**Comments**

**Staff Initials**

**Dangerous Substances:**

Have been identified

bleach (cleaning)

LE

Emergency plan in place

\_\_\_\_\_

LE

Sanitation

\_\_\_\_\_

LE

Washrooms meet standards

\_\_\_\_\_

LE

MSDS posted

in your cupboard

LE

**Electrical:**

Switches and outlets have plate covers

\_\_\_\_\_

LE

Electrical cords in good condition

N/A

-

**Emergency Preparedness:**

Emergency plan in place

\_\_\_\_\_

LE

Stocked first aid kits available

\_\_\_\_\_

LE

Regularly inspected fire extinguishers/alarms

September 2023

LE

**Playground:**

Check for ice control

N/A

-

Check for foreign objects

\_\_\_\_\_

LE

Check playground equipment

\_\_\_\_\_

LE

Check surfaces

\_\_\_\_\_

LE

Check gate latches

\_\_\_\_\_

LE

**Other:**

→ hole in playground fence  
~ reported to school on  
Sept 21/23.  
by onsite Admin

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

→ heater falling off wall → reported to school



Date of inspection: Sept 29/23

Inspected by: Lou Evans

