



St. Teresa's  
SACC

YMCA of Newfoundland and Labrador

Avalon Peninsula Region  
35 Ridge Road, P.O. Box 21291  
St. John's, NL A1A 5G6  
Tel: 709-726-9622  
www.ymcanl.com CRA#108225533RR0001

### Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
<b>Exits:</b>		
Signage present	_____	<u>LE</u>
Width, wheelchair accessibility	_____	<u>LE</u>
Ice Control	<u>Salt road walk ways</u>	<u>LE</u>
Direction of openings	_____	<u>LE</u>
Mechanical hardware	_____	<u>LE</u>
Doors kept close	_____	<u>LE</u>
<b>Ergonomics:</b>		
Repetitive movements required	_____	<u>LE</u>
Use proper lifting techniques	_____	<u>LE</u>
<b>Stacking/Storage:</b>		
Safe storage area and containers	_____	<u>LE</u>
Safe arrangement of equipment and materials	_____	<u>LE</u>
Equipment in safe working condition	_____	<u>LE</u>
<b>Aisles/Passageways:</b>		
Clear of clutter	_____	<u>LE</u>
Adequate lighting	_____	<u>LE</u>
No tripping hazards	_____	<u>LE</u>



Checklist Items

Comments

Staff Initials

**Dangerous Substances:**

Have been identified

locked & cabinets

LE

Emergency plan in place

\_\_\_\_\_

LE

Sanitation

\_\_\_\_\_

LE

Washrooms meet standards

\_\_\_\_\_

LE

MSDS posted

\_\_\_\_\_

LE

**Electrical:**

Switches and outlets have plate covers

\_\_\_\_\_

LE

Electrical cords in good condition

\_\_\_\_\_

LE

**Emergency Preparedness:**

Emergency plan in place

\_\_\_\_\_

LE

Stocked first aid kits available

\_\_\_\_\_

LE

Regularly inspected fire extinguishers/alarms

\_\_\_\_\_

LE

**Playground:**

Check for ice control

\_\_\_\_\_

LE

Check for foreign objects

\_\_\_\_\_

LE

Check playground equipment

\_\_\_\_\_

LE

Check surfaces

\_\_\_\_\_

LE

Check gate latches

\_\_\_\_\_

LE

**Other:**

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_



Date of inspection: DEC 06, 2023

Inspected by: Lell Evans

