



St. Peter's
SACC

Avalon Peninsula Region
35 Ridge Road, P.O. Box 21291
St. John's, NL A1A 5G6
Tel: 709-726-9622
www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

<u>Checklist Items</u>	<u>Comments</u>	<u>Staff Initials</u>
Exits:		
Signage present	_____	LE
Width, wheelchair accessibility	_____	LE
Ice Control	walkways salted	LE
Direction of openings	_____	LE
Mechanical hardware	_____	LE
Doors kept close	_____	LE
Ergonomics:		
Repetitive movements required	_____	LE
Use proper lifting techniques	_____	LE
Stacking/Storage:		
Safe storage area and containers	_____	LE
Safe arrangement of equipment and materials	_____	LE
Equipment in safe working Condition	_____	LE
Aisles/Passageways:		
Clear of clutter	_____	LE
Adequate lighting	_____	LE
No tripping hazards	_____	LE



Checklist Items

Comments

Staff Initials

Dangerous Substances:

Have been identified

bleach → stored in Cathy's cupboards. LE

Emergency plan in place

_____ LE

Sanitation

_____ LE

Washrooms meet standards

_____ LE

MSDS posted

_____ LE

Electrical:

Switches and outlets have plate covers

_____ LE

Electrical cords in good condition

taped to the wall (up off the floor) LE

Emergency Preparedness:

Emergency plan in place

_____ LE

Stocked first aid kits available

_____ LE

Regularly inspected fire extinguishers/alarms

Aug 2023. July (LE)

Playground:

Check for ice control

_____ LE

Check for foreign objects

_____ LE

Check playground equipment

_____ LE

Check surfaces

_____ LE

Check gate latches

_____ LE

Other:

bags of ice control sealed by the door
tiles missing due to previous leaks → called school.



Date of inspection: DEC 07, 2023

Inspected by: Low Evans

