

Supervision. Responsibility includes ensuring that facilities (including rental sites) receive adequate specific work task training.



Juniper Ridge
SACC

YMCA of Newfoundland and Labrador

Avalon Peninsula Region
35 Ridge Road, P.O. Box 21291
St. John's, NL A1A 5G6
Tel: 709-726-9622
www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site

Checklist Items

Staff Initials

Exits:

- Signage present
- Width, wheelchair accessibility
- Ice Control
- Direction of openings
- Mechanical hardware
- Doors kept close

TB
TB
N/A
TB
TB
TB

Comments

outwards
Yes

Ergonomics:

- Repetitive movements required
- Use proper lifting techniques

TB
TB

Stacking/Storage:

- Safe storage area and containers
- Safe arrangement of equipment and materials
- Equipment in safe working Condition

TB
TB
TB

Aisles/Passageways:

- Clear of clutter
- Adequate lighting
- No tripping hazards

TB
TB
TB

Building healthy communities

October, 2024



Checklist Items

Comments

Staff Initials

Dangerous Substances:

- Have been identified
- Emergency plan in place
- Sanitation
- Washrooms meet standards
- MSDS posted

TB
TB
TB
TB
TB

Need new signage

Electrical:

- Switches and outlets have plate covers
- Electrical cords in good condition

TB
TB

Emergency Preparedness:

- Emergency plan in place
- Stocked first aid kits available
- Regularly inspected fire extinguishers/alarms

TB
TB
TB

Sept 2023

Playground:

- Check for ice control
- Check for foreign objects
- Check playground equipment
- Check surfaces
- Check gate latches

N/A
TB
TB
TB
N/A

Other:

Exit door does not
open all the way

P

Jason Brown, CEO



Date of inspection: September 10th, 2024

Inspected by: Taylor Butt

information is updated at least annually and may be