



YMCA of Newfoundland and Labrador

Avalon Peninsula Region
35 Ridge Road, P.O. Box 21291
St. John's, NL A1A 5G6
Tel: 709-726-9822
www.ymcanl.com CRA#108225533RR0001

Bay Roberts Primary SACC

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site #4

Checklist Items Initials	Comments	Staff
Exits:		
Signage present	_____	DS
Width, wheelchair accessibility	_____	DS
Ice Control	Done by school	DS
Direction of openings	outward	DS
Mechanical hardware	_____	DS
Doors kept close	_____	DS
Ergonomics:		
Repetitive movements required	_____	DS
Use proper lifting techniques	_____	DS
Stacking/Storage:		
Safe storage area and containers	_____	DS
Safe arrangement of equipment and materials	_____	DS
Aisles/Passageways:		
Adequate width	_____	DS
Clear of clutter	_____	DS
Adequate lighting	_____	DS
Clear signage	_____	DS
Doors have windows	_____	DS
No tripping hazards	_____	DS

Checklist Items

Initials

Ladders:

In good condition

Comments

NA

Staff

DS

Correct type for job

Spacing of rungs

Are items stored over head in a safe manner?

Are materials stored clear of sprinkler heads?

Dangerous Substances:

Have been identified

Cleaner

DS

Emergency plan in place

DS

Sanitation

DS

Washrooms meet standards

cleaned by school

DS

Kitchens or food preparation areas meet

standards

NA

DS

MSDS posted

DS

Licensed Child Care Workplace Inspection

DS

Checklist

Electrical:

Switches and outlets have plate covers

DS

All breakers identified

Access to electrical panels unobstructed

Electrical cords in good condition

none present

DS

Emergency Preparedness:

Emergency plan in place

DS

Stocked first aid kits available

DS

Regularly inspected fire extinguishers/alarms

by school

DS

Sprinkler system

by school

DS

Emergency suppression system

DS

Checklist Items

Staff Initials

Playground:

Check for ice control

Done by School

DS

Check for foreign objects

DS

Check playground equipment

daily

DS

Check surfaces

Check gate latches

DS
gate chain needs repair DS

Office Space:

Clear of clutter

NA DS

Adequate lighting

No tripping hazards

Date of inspection: Dec 10/24

Inspected by: Denev Snook