

## YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

## **Licensed Child Care Workplace Inspection Checklist**

Firm # 2038622 Site #4 BISHOP FEILD Checklist Items Staff Initials **Comments** Exits: Signage present Width, wheelchair accessibility SCHOOL NOT ACCESSIBLE Ice Control SCHOOL MAINTAINS Direction of openings Mechanical hardware Doors kept close **Ergonomics:** Repetitive movements required Use proper lifting techniques Stacking/Storage: Safe storage area and containers Safe arrangement of equipment and materials Aisles/Passageways: Adequate width Clear of clutter Adequate lighting Clear signage Doors have windows

No tripping hazards



| Checklist Items                                | Comments | Staff Initials |
|--|----------|----------------|
| Ladders:                                       |          |                |
| In good condition                              |          |                |
| Correct type for job                           |          | <u></u>        |
| Spacing of rungs                               |          | <u>(e)</u>     |
| Are items stored over head in a safe manner?   |          | <u>(e)</u>     |
| Are materials stored clear of sprinkler heads? |          | ( <u>@</u> )   |
|  |          |                |
| Dangerous Substances:                          |          |                |
| Have been identified                           |          |                |
| Emergency plan in place                        |          |                |
| Sanitation                                     |          |                |
| Washrooms meet standards                       |          | (OR)           |
| Kitchens or food preparation areas meet        |          |                |
| standards                                      |          |                |
| MSDS posted                                    |          | <u>(CP)</u>    |
| Licensed Child Care Workplace Inspection       |          |                |
| Checklist                                      |          | (e)            |
|  |          |                |
| Electrical:                                    |          |                |
| Switches and outlets have plate covers         |          |                |
| All breakers identified                        |          |                |
| Access to electrical panels unobstructed       |          | (CB)           |
| Electrical cords in good condition             |          |                |
|  |          |                |
| Emergency Preparedness:                        |          |                |
| Emergency plan in place                        |          |                |
| Stocked first aid kits available               |          | ( <u>cre)</u>  |
| Regularly inspected fire extinguishers/alarms  |          |                |
| Sprinkler system                               |          |                |
| Emergency suppression system                   |          |                |



| Checklist Items            | <u>Comments</u> | Staff Initials |
|----------------------------|-----------------|----------------|
| Playground:                |                 |                |
| Check for ice control      | SCHOOL BOGS     | (ce)           |
| Check for foreign objects  |                 | <u>6e</u> )    |
| Check playground equipment |                 |                |
| Check surfaces             |                 |                |
| Check gate latches         |                 | <u></u>        |
|                            |                 |                |
| Office Space:              |                 |                |
| Clear of clutter           |                 | <u>(e)</u>     |
| Adequate lighting          |                 | <u>@</u> _     |
| No tripping hazards        |                 | <u> </u>       |

Date of inspection: 14 11 24

Inspected by: CONRAD RACICOT (R)