YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site #4 Checklist Items Comments Staff <u>Initials</u> Exits: Signage present Width, wheelchair accessibility Ice Control Direction of openings Mechanical hardware sp Doors kept close Ergonomics: Repetitive movements required SP Use proper lifting techniques Stacking/Storage: Safe storage area and containers SD Safe arrangement of equipment SD and materials SD Aisles/Passageways: SD Adequate width 50 Clear of clutter Adequate lighting Clear signage Doors have windows

	tripp			a week or
4 4 11	Sec. 15. 25	+ 173.63	Daz	

Checklist Items	Comments	Staff
Initials Ladders:		SO
In good condition		- CO
Correct type for job	-	26
Spacing of rungs		- 50
Are items stored over head in a safe manner?	Telling and the second	59
Are materials stored clear of sprinkler heads?	-	-50
Dangerous Substances:		
Have been identified		20
Emergency plan in place		-
Sanitation	/- <u></u>	SO
Washrooms meet standards Kitchens or food preparation areas meet		So
standards		75
MSDS posted		30
Licensed Child Care Workplace Inspection		
Checklist Electrical:		SO
Switches and outlets have plate covers		SD
All breakers identified		SD
Access to electrical panels unobstructed		
Electrical cords in good condition		_
3/11/11/19/2		
Emergency Preparedness:		
mergency plan in place		-z>
tocked first aid kits available		SD
Regularly inspected fire extinguishers/alarms	Sept 23/23	
Sprinkler system		- S.P
Emergency suppression system		

Checklist Items Staff Initials Playground:	Comments •	
Check for ice control		
Check for foreign objects		
Check playground equipment	52	
Check surfaces		
Check gate latches	SC)
Office Space:		
Clear of clutter	SD)
Adequate lighting	>D S	>
No tripping hazards		

Date of inspection: Dec 9 2024

Inspected by: Sharlean Ogy