

YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site #4 PARWISE

Checklist Items	Comments	Staff Initials
Exits: Signage present Width, wheelchair accessibility Ice Control Direction of openings Mechanical hardware Doors kept close	SCHOOL MANAGES	88888
Ergonomics: Repetitive movements required Use proper lifting techniques		(A)
Stacking/Storage: Safe storage area and containers Safe arrangement of equipment and materials		(CR)
Aisles/Passageways: Adequate width Clear of clutter Adequate lighting Clear signage Doors have windows No tripping hazards		



Checklist Items	Comments	Staff Initials
Ladders:		
In good condition		
Correct type for job		
Spacing of rungs		
Are items stored over head in a safe manner?		
Are materials stored clear of sprinkler heads?		<u>(Ce)</u>
Dangerous Substances:		
Have been identified		
Emergency plan in place		<u> </u>
Sanitation		
Washrooms meet standards		<u></u>
Kitchens or food preparation areas meet		
standards		
MSDS posted		
Licensed Child Care Workplace Inspection		
Checklist		
Electrical:		
Switches and outlets have plate covers		
All breakers identified		
Access to electrical panels unobstructed		
Electrical cords in good condition		
Emergency Preparedness:		
Emergency plan in place		
Stocked first aid kits available		
Regularly inspected fire extinguishers/alarms		
Sprinkler system		
Emergency suppression system		



Checklist Items	Comments	Staff Initials
Playground:		
Check for ice control	SCHOOL MANAGES	
Check for foreign objects	<u> </u>	(P)
Check playground equipment		
Check surfaces		(CP)
Check gate latches		
Office Space:		
Clear of clutter		
Adequate lighting		
No tripping hazards		(do)

Date of inspection: 18 12 24

Inspected by Conrad Racicot CR