

YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site #4 ST. TERESA'S

Checklist Items	Comments	Staff Initials
Exits: Signage present Width, wheelchair accessibility Ice Control Direction of openings Mechanical hardware Doors kept close	SCHOOL DOES	888 888 888
Ergonomics: Repetitive movements required Use proper lifting techniques		CR)
Stacking/Storage: Safe storage area and containers Safe arrangement of equipment and materials		@
Aisles/Passageways: Adequate width Clear of clutter Adequate lighting Clear signage		
Doors have windows No tripping hazards		<u>(P</u>



Checklist Items	Comments	Staff Initials	
Ladders:			\bigcirc
In good condition			(CR)
Correct type for job			(ce)
Spacing of rungs			(œ)
Are items stored over head in a safe manner?			60
Are materials stored clear of sprinkler heads?			(ce)
Dangerous Substances:			
Have been identified			(ce)
Emergency plan in place			(de)
Sanitation			æ
Washrooms meet standards			(DE)
Kitchens or food preparation areas meet			_
standards			_(R)
MSDS posted			6e)
Licensed Child Care Workplace Inspection			
Checklist			<u>(</u>
Electrical:			
Switches and outlets have plate covers			(OR)
All breakers identified			P
Access to electrical panels unobstructed			æ
Electrical cords in good condition			(H)
Emergency Preparedness:			
Emergency plan in place			(CR)
Stocked first aid kits available			GR)
Regularly inspected fire extinguishers/alarms			(R)
Sprinkler system			(CP)
Emergency suppression system			(00)



Checklist Items	Comments	Staff Initials
Playground:		
Check for ice control	SCHOOL DOGS	(P)
Check for foreign objects		(P)
Check playground equipment		(R)
Check surfaces		<u>6</u>
Check gate latches		(00)
Office Space:		
Clear of clutter		
Adequate lighting		60
No tripping hazards		(QC)

Date of inspection: 27 11 2024

Inspected by: Conrad Racicot (R