

## YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

## Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site:		
Checklist Items	Comments	Staff Initials
Exits:	1.2	HW
Signage present	Ves.	111.3
Width, wheelchair accessibility	165	- HW
Ice Control	Ves Ves	Hlad
Direction of openings	165	
Mechanical hardware	165	<u>HW</u>
Doors kept close	Yes	<u>HW</u>
Ergonomics:		111
Repetitive movements required	115	_ HW
Use proper lifting techniques	165	- HW
Stacking/Storage:		11)
Safe storage area and containers	<u> </u>	_ HW
Safe arrangement of equipment		
and materials	<u>Ves</u>	_ HW
Aisles/Passageways:		.,
Adequate width —	Ves	
Clear of clutter	VES VES	HW.
Adequate lighting	Ves	- HW
Clear signage	Je5	_ HW
Doors have windows	Some not all	HW
No tripping hazards	VES	HW



Checklist Items	Comments	Staff Initials
Ladders:		111-1
In good condition	165	HW
Correct type for job	\UZ	HW.
Spacing of rungs	100	HIV
Are items stored over head in a safe manner?	115	HW /
Are materials stored clear of sprinkler heads?	117	HW
Dangerous Substances:	1//	1110/
Have been identified	NIA	HVV
Emergency plan in place	100	<u> </u>
Sanitation	125	HW
Washrooms meet standards	125	HW
Kitchens or food preparation areas meet		111. /
standards	YES	HW
MSDS posted	<u> 145</u>	
Licensed Child Care Workplace Inspection		
Checklist	125	
Electrical:		
Switches and outlets have plate covers	VES	HW
All breakers identified		<u>HW</u>
Access to electrical panels unobstructed	ies	HW
Electrical cords in good condition	Ves	<u>HW</u>
Liectrical corus in good condition		
Emergency Preparedness:		
	1115	HW.
Emergency plan in place	1125	- HW
Stocked first aid kits available	NPS	HW-
Regularly inspected fire extinguishers/alarms	100 1111	11. =1.5
Sprinkler system	YES I'N HE	May My
Emergency suppression system	185	1100



Checklist Items	Comments	Staff Initials
Playground:		b. 1
Check for ice control	165	<u>HW</u>
Check for foreign objects	<u> 165</u>	HW
Check playground equipment	189	HW HW
Check surfaces	Yes	HW.
Check gate latches	ils	HW.
Office Space:		
Clear of clutter	Ves	
Adequate lighting	Ves	
No tripping hazards	Ve3	

Date of inspection: Dec 6, 2024

Inspected by: Heather Wirth