

YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site COWAN	MEIGHTS	
Checklist Items	Comments	Staff Initials
Exits:		
Signage present		
Width, wheelchair accessibility		
Ice Control		(P)
Direction of openings		
Mechanical hardware		<u></u>
Doors kept close		(cr)
Ergonomics:		
Repetitive movements required		(ce)
Use proper lifting techniques		<u>6</u> e
Stacking/Storage:		
Safe storage area and containers		
Safe arrangement of equipment		
and materials		<u>CP</u>
Equipment in safe working		\bigcirc
Condition		<u>(a)</u>
Aisles/Passageways:		2
Clear of clutter		
Adequate lighting		Ge
No tripping hazards		ED I

Building healthy communities



Checklist Items	Comments	Staff Initials
Dangerous Substances:		
Have been identified		
Emergency plan in place		<u>(p)</u>
Sanitation		
Washrooms meet standards		(CR)
MSDS posted		_ (CE)
Electrical:		
Switches and outlets have plate covers		
Electrical cords in good condition		
Emergency Preparedness:		
Emergency plan in place		
Stocked first aid kits available		
Regularly inspected fire extinguishers/alar	ms	
Playground:	1	63
Check for ice control	N/A BY SCHOOL	
Check for foreign objects		
Check playground equipment		
Check surfaces	4	
Check gate latches	N/A NO GATE	
Other:		
	SUDING DOOR IN ROOM	
	REPORTED TO SCHOOL	
	and to the second of the secon	



Date of inspection: CONRAD RACICOT (R)

Inspected by: 11 | 9 | 24