

YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site RONCALL 1

Checklist Items	Comments	Staff Initials
Exits:		
Signage present		<u></u>
Width, wheelchair accessibility		
Ice Control	School Does	<u>CR</u>
Direction of openings	Y	<u> </u>
Mechanical hardware	9	
Doors kept close		
Ergonomics:		
Repetitive movements required		
Use proper lifting techniques		<u>de</u>
Stacking/Storage:		
Safe storage area and containers		<u> </u>
Safe arrangement of equipment		
and materials		(P)
Equipment in safe working		
Condition		_
Aisles/Passageways:		
Clear of clutter		
Adequate lighting		
No tripping hazards		_ (ce

Building healthy communities



Checklist Items	Comments	Staff Initials
Dangerous Substances:		
Have been identified		62
	2	_
Emergency plan in place Sanitation		@
Washrooms meet standards	-	
MSDS posted		
Electrical:		
Switches and outlets have plate covers		
Electrical cords in good condition		
Emergency Preparedness:		
Emergency plan in place		
Stocked first aid kits available		
Regularly inspected fire extinguishers/alarm		
Playground:		
Check for ice control	SHOOL DOES	
Check for foreign objects		
Check playground equipment		(P)
Check surfaces		60
Check gate latches		
Circus Base rateries		
Other:		
	GAPS UNDER FENCE IN	<u> </u>
	2 SPOTS REPORTED TO	
	SHE SCHOOL	
	to coupt. Player	

V

Date of inspection: 1992

Inspected by: CONRAD RACICOT CR