

## YMCA of Newfoundland and Labrado

Avalion Peninsula Region 35 Bidge Boad, P.O. Box 21291 St. John's, Nt. A1A SG6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

## Licensed Child Care Workplace Inspection Checklist

Firm # 2038622 Site ##		
Checklist Items	Comments	Staff Initials
Entre		
Signage present		<u>SE</u>
Width, wheelchair accessibility		
Ice Control	computed byschool	
Direction of openings	cutwards	<u>5</u> E
Mechanical hardware		
Doors kept close		<u>5€</u>
Ergonomics:		
Repetitive movements required		SE_
Use proper lifting techniques		_ 5€
Stacking/Storage:		
Safe storage area and containers		5E
Safe arrangement of equipment		
and materials		SE
Aisles/Passageways:		
Adequate width		5E
Clear of clutter		SE.
Adequate lighting		
Clear signage		
Doors have windows		<u>3E</u>
No tripping hazards		- SE
to tripping flatarus		SE

Building healthy communities



Checklist Items	Comments	Staff Initials
Ladders:		1
In good condition	NA	
Correct type for job	NA	
Spacing of rungs	NA	
Are items stored over head in a safe	manner? Yes	SE_
Are materials stored clear of sprinkl	er heads? Yes	<u>SE</u>
Dangerous Substances:		
Have been identified	all safe	
Emergency plan in place		<u>SE</u>
Sanitation		<u> 5E</u>
Washrooms meet standards		<u>5E</u>
Kitchens or food preparation areas n		
standards	NIA	<u>SE</u>
MSDS posted		<u>5E</u>
Licensed Child Care Workplace Inspe	ection	
Checklist	-	SE_
Electrical:		
Switches and outlets have plate cover	ers	5E
All breakers identified	NA	3E
Access to electrical panels unobstruc	tted NA	SE
Electrical cords in good condition	NA	3€
Emergency Preparedness:		
		er
Emergency plan in place		<u>SE</u>
Stocked first aid kits available		<u>5</u> E_
Regularly inspected fire extinguishers	s/alarms NA	<u>5E</u>
Sprinkler system	NA	<u>SE</u>
Emergency suppression system	NA	5E



Checklist Items	Comments	Staff Initials
Playground:		
Check for ice control	MIA	SE_
Check for foreign objects		SE
Check playground equipment		SE
Check surfaces		<u>SE</u>
Check gate latches		
Office Space:	NA	SE
Clear of clutter	NA	SE
Adequate lighting	NA	<u>SE</u> <u>SE</u> SE
No tripping hazards	1010	

Date of inspection: 12/19/24

Inspected by: Sean Evans