

YMCA of Newfoundland and Labrador

Avalon Peninsula Region 35 Ridge Road, P.O. Box 21291 St. John's, NL A1A 5G6 Tel: 709-726-9622 www.ymcanl.com CRA#108225533RR0001

Licensed Child Care Workplace Inspection Checklist

		_
Firm # 2038622 Site CC	ivary Baptist Jan 6/2025	7
Checklist Items	Comments	Staff Initials
Exits: Signage present Width, wheelchair accessibility Ice Control Direction of openings Mechanical hardware	NIA Outward mainderer Closed and locked	888 888 888 888 888 888 888 888 888 88
Doors kept close	Cose and locker	<u> </u>
Ergonomics: Repetitive movements required Use proper lifting techniques	will add posters	<u>8W</u>
Stacking/Storage: Safe storage area and containers Safe arrangement of equipment and materials Equipment in safe working Condition	Church has Chairs Stacked in room along wall	<u>800</u> 800
Aisles/Passageways: Clear of clutter Adequate lighting No tripping hazards	Baskets to Side of walk to keep main walk way clear	510 510



Checklist Items	Comments	Staff Initials	
Dangerous Substances: Have been identified Emergency plan in place Sanitation Washrooms meet standards MSDS posted	labeled on board posted in cup	SW SW Sward	
Electrical: Switches and outlets have plate covers Electrical cords in good condition		- 8W 8W	
Emergency Preparedness: Emergency plan in place Stocked first aid kits available Regularly inspected fire extinguishers/alarms	-	aids sw	
Playground: Check for ice control Check for foreign objects Check playground equipment Check surfaces Check gate latches	NIA Kaldrin noticed Swi 100 Ked unsafe, not and notified Schor	Nessing SW SW SW SW SW	
Other:			



Date of inspection: 5an 6/2025
Inspected by: 8. White Melae

	₹.		